TAG-Out your Meters that are not in use or not working (CNSC Recommendation) Nov 2008

<u>Contamination meters</u> not in use should be identified as such. It was recommended that the meters be clearly labelled to identify the unit as not in use and to indicate the reason. The tag below was created to be placed over the glass display window on the meter. Remember, only properly functioning units may be used for contamination monitoring or personal monitoring.

- If the EHS calibration verification sticker is no longer valid. Send an email to radsafety@umanitoba.ca to arrange to have the meter's calibration verified!
 The verification is only valid for 36 months. The sticker indicates the meter and probe combination for a specific radioisotope in use (e.g. P32, F18, Tc99m).
- If you require assistance in arranging a working meter, contact Environmental Health & Safety.
- If the meter is not working, the unit (probe & meter) can be sent for repair and/or recalibration. Companies that provide this service are:

Stuart Hunt:

https://www.stuarthunt.com/services/survey-meter-calibration--repair

Stuart Hunt & Associates (authorized Ludlum Dealer) 15803 – 145 Avenue N.W. Edmonton, Alberta T6V 0H8 1-800 661-4591

Ludlum Measurements:

https://ludlums.com/repair-calibration-lmi-sweetwater-tx

Ludlum Measurements, Inc. Attn: Repair and Calibration 501 Oak Street Sweetwater, Texas 79556 1-800 662-0828

If you are not using your meter, "tag it out" so that you won't be cited!

Do Not Use Contamination Meter
Do not remove tag until:
Calibration Verified by EHS
Meter/Probe/Cable Repaired
Battery Changed \Box
Unit Re-calibrated □
Date:
(call EHS 474-6633)